

A low-angle photograph of a construction site. A large, white metal frame is being lowered into place by a crane. The frame is suspended by several thick cables. In the background, a multi-story building with a brick and white facade is visible. Three construction workers in yellow shirts and hard hats are standing on the roof of the building. The sky is blue with some clouds.

Falls Schools **Facilities Assessment**

Completed in 2014 in partnership with
Eppstein Uhen Architects

TABLE OF CONTENTS

SECTION 1 Executive Summary

SECTION 2 Site and Building Capacity

- a) Site Capacity
- b) Building Capacity
- c) Building Utilization (MS & HS)
- d) Americans with Disabilities Act (ADA) Study

SECTION 3 Educational Adequacy Assessments - by School

- A. Ben Franklin Elementary School
- B. Riverside Elementary School
- C. Shady Lane Elementary School
- D. Valley View Elementary School
- E. North Middle School
- F. Menomonee Falls High School

SECTION 4 Site and Building Inspection Summary - by Building

- A. Ben Franklin Elementary School
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Plumbing Inspection Report – Muermann Engineering
 - vi. ADA Compliance Report
 - vii. Building System Lifespan Comparison (graphic)
- B. Riverside Elementary School
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Plumbing Inspection Report – Muermann Engineering
 - vi. ADA Compliance Report
 - vii. Building System Lifespan Comparison (graphic)
- C. Shady Lane Elementary School
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Plumbing Inspection Report – Muermann Engineering
 - vi. ADA Compliance Report
 - vii. Building System Lifespan Comparison (graphic)

- D. Valley View Elementary School
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Plumbing Inspection Report – Muermann Engineering
 - vi. ADA Compliance Report
 - vii. Building System Lifespan Comparison (graphic)
- E. North Middle School
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Plumbing Inspection Report – Muermann Engineering
 - vi. ADA Compliance Report
 - vii. Building System Lifespan Comparison (graphic)
- F. Menomonee Falls High School
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Electrical Inspection Athletic Stadium Report – Muermann Engineering
 - vi. Plumbing Inspection Report – Muermann Engineering
 - vii. ADA Compliance Report
 - viii. Building System Lifespan Comparison (graphic)
- G. Thomas Jefferson School
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Plumbing Inspection Report – Muermann Engineering
 - vi. ADA Compliance Report
 - vii. Building System Lifespan Comparison (graphic)
- H. Menomonee Falls Community Center
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA
 - iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering – SEE RIVERSIDE
 - iv. Electrical Inspection Report – Muermann Engineering
 - v. Plumbing Inspection Report – Muermann Engineering – SEE RIVERSIDE
 - vi. ADA Compliance Report
 - vii. Building System Lifespan Comparison (graphic)
- I. Hiawatha Building
 - i. Historical Plan and Site Plan
 - ii. Building Inspection Report – EUA

- iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
- iv. Electrical Inspection Report – Muermann Engineering
- v. Plumbing Inspection Report – Muermann Engineering
- vi. ADA Compliance Report
- vii. Building System Lifespan Comparison

J. Maintenance Building

- i. Site Plan
- ii. Building Inspection Report – EUA
- iii. Heating, Ventilation and Air Conditioning Inspection Report – Fredericksen Engineering
- iv. Electrical Inspection Report – Muermann Engineering

SECTION 5 Appendices

- a) District Map
- b) Articles
 - 1. Do School Facilities Affect Academic Outcomes? – *Mark Schneider*
 - 2. Educational Trends Shaping School Planning, Design, Construction, Funding and Operation – *Kenneth Stevenson*
 - 3. School Facility Conditions and Student Academic Achievement – *Glen Earthman*
 - 4. Flipped Classrooms Spreading in Wisconsin – *Matthew Defour, Wisconsin State Journal*
 - 5. 2011 ASHRAE Handbook – HVAC Applications
- c) Reference Reports (by others)
 - 1. Auditoriums
 - i. Professional Audio Designs Inc. – AV Systems
 - ii. Main Stage – Theatre Equipment
 - iii. JWC Building Specialties, Inc. - Seating
 - 2. Roof Inspection Report – Industrial Roofing Service, Inc.
 - 3. Asphalt Inspection Report – Industrial Roofing Service, Inc.
 - 4. Exterior Walls Report – Industrial Roofing Service, Inc.
 - 5. North Middle School Library Furniture layout – Bretford Manufacturing, Inc.